dataclinic

The Pavilions, Bridge Hall Lane, Bury, Manchester
0800 151 2207 · customerservices@dataclinic.co.uk
www.dataclinic.co.uk · ICO registered

SAMPLE — FOR ILLUSTRATION ONLY — FICTIONAL DATA — NOT A VALID CERTIFICATE

Recovery-Verified Certificate of Destruction

Destroyed, then tested by data recovery engineers — and certified unrecoverable.

Certificate no.	SAMPLE-CERT-0000	**Job reference**	SAMPLE-DD-00000
Customer	Example Organisation Ltd (fictional)	**Devices**	2
Received	01-01-2000 (sample date)	**Certificate issued**	01-01-2000 (sample date)
Received by	Free DPD collection — chain of custody logged	**Location**	Data Clinic lab, Bury, Manchester

Device record

#	Device	Make / model	Serial no.	Destruction method	Recovery-verification result
1	3.5" hard drive	EXAMPLE MAKE / MODEL	SAMPLE-SN-0001	Physical destruction — platter shredding	**NO DATA RECOVERABLE** Recovery attempted by our engineers; no readable data
2	2.5" SSD	EXAMPLE MAKE / MODEL	SAMPLE-SN-0002	Physical destruction — crushing / shredding	**NO DATA RECOVERABLE** Recovery attempted by our engineers; no readable data

How this certificate was earned

1. Chain of custody — each device logged by serial number on arrival at our Bury lab.

2. Destruction — by the method recorded above, chosen to suit the customer's compliance needs.

3. Recovery verification — the same engineers who recover data from fire-damaged, water-damaged and wiped media attempted recovery on each destroyed device and recorded the result.

4. Certification — this certificate is issued per job, with a line for every device, and retained on our systems for 6 years.

We certify that the devices listed above were destroyed by Data Clinic Ltd by the stated method, and that a subsequent recovery attempt by our data recovery engineers recovered no data from any of them.

Destruction engineer (sample) | Verification engineer (sample) | Date (sample)

SAMPLE